

The equipment must be checked for correct operation and safety, especially the points listed below:

Proof of maintenance

Function

1. Make sure the pump mechanism moves smoothly.
2. Check water hoses for wear and tear; replace if necessary. To do this, loosen lid bolts (Allen key No. 4) and remove upper part including pump mechanism.
3. Clean sieve of pressure reduction valve if soiled.

Valve and cartridge


4. When replacing the entire valve or the cartridge, pump several times until the automatic shutoff engages (if necessary, shut off the water several times and then turn on again).

- ## Structural stability

Check anchoring to the ground every 12 months, retighten screws and bolts if necessary.

Note

Prior to the start of the frost period, turn off water supply and remove the mushroom pump. It is necessary to remove at least the upper part. If the housing part is to remain on site, you may order a winter lid (**No. 0.97840**) from us.




For spare parts refer to next page.

Maintenance carried out by:

..... **Date**

Special notes, e.g. for repairs

Spare parts
Mushroom Spring
Order No. 5.18000-5.18005




Please note that the safety standards of the equipment must not be affected. Therefore, when carrying out repairs it is helpful to **only use original parts**.

Order No. Spare parts

Order No. Spare parts


0.97833 Self-righting pressure valve
 (valid until June 2022)
please request repair instructions for replacement




0.97834 Replacement cartridge for self-righting pressure valve
 (valid until June 2022)
please request repair instructions for replacement



0.97841 Self-righting pressure valve
 (valid from December 2023)
please request repair instructions for replacement




0.97842 Replacement cartridge for self-righting pressure valve
 (valid from December 2023)
please request repair instructions for replacement



0.97835 Connecting hose with hose protection



0.97836 Pressure reducer



0.97837 Seal for hose connection



0.97840 Winter lid

