
| Instructions for wear checks of play equipment | o | The equipment must be checked for correct operation and safety, especially the points listed below: | | Proof of maintenance | |
|--|----------|---|--|---------------------------------|--|
| Playground | | Bolts | | | |
| Date of installation | 1. | Check that bolts are tight & retighten if necessary. | | | |
| Checks depend on the type of equipment. | | Travelling crab | | | |
| Any equipment with moving parts must be checked at least twice a year, static equipment at least once a year. | 2. | damage. Replace damaged parts if necessary. | | | |
| Intervals for maintenance work and checks | | Carrying cable/cable connection | | | |
| generally depend on | 3. | Check cable for damage & replace if necessary. | | | |
| - the location - the usage | 4. | Check articulated cable connection (mountain station) for wear. | | | |
| the disage the frequency of use possible vandalism For more details see also "General instructions for maintenance of playgrounds". | 5. | Check the slack when no load is placed on the cable by measuring the distance between the line of view and the cable with the assistance of a second person performing the measurement at the check point (= 1.00 m). Re-tension cable according to the sketch. | | | |
| Grand Arch Cableway up to 30 m Order No. 6.01110 | 6. 7. | 9 | | | |
| mountain station (a) (b) (c) (d) (e) (f) (f) (f) (f) (g) (g) (g) (g | | 40 cm min. with no load placed on the seat (1st check 1 week after assembly, 2nd check 4 weeks after assembly, after this regular maintenance intervals), adjust ground if necessary. | | | |
| at least 40 cm | 8. | Structural stability Uncover the foundation once a year in order to check for corrosion. | | | |
| 8 check point approx. 14 m from valley station suspension Re-tensioning | | valley station | | Special notes, e.g. for repairs | |
| Apply tube (Ø 20 mm, approx. 50 cm long) and remove safety bolts. Tension with no load placed on cable until slack = 1.00 m. Refasten the safety bolts. The cable must be wound around at least 2 times. | | 8 | | Special note | |
| | | epair not carried out, is still possible to play on equipment | | | |
| | | epair not carried out, quipment is taken out of action | | | |
| 5 | 1 | II work carried out, verything is in order | | | |
| tube Ø 20 mm | M | Maintenance carried out by: | | | |
| /// \\ | | Date | | | |

Spare Parts Grand Arch Cableway Order No. 6.01110



Please note that the safety standards of the equipment must not be affected. Therefore, when carrying out repairs it is helpful to **only use original parts**.

Order No. Spare part Order No. Spare part 0.95000 pendulum seat with suspension 0.95051 stopper spring for mountain station chain length 1.50 m 0.95052 stopper spring for valley station 0.95015 rubber buffer for travelling crab with sound muffler $((\circ)$ 0.95012 travelling crab 0.94110 pendulum seat without disc 0.94120 disc for pendulum seat 0.95020 carrying cable 34 m with 2 hose sleeve segments