

Kontrollnachweis

A detailed line drawing of a mobile structure. It features a horizontal beam (1) supported by a triangular frame (2) on the left and a vertical post (5) on the right. A small cylindrical weight (3) is suspended from the beam by a string (4). A vertical arrow (6) indicates a distance of 40 cm from the weight to a horizontal bar (7). The entire structure is mounted on a base (9). To the right, a separate vertical frame (8) is shown, which appears to be a support for the main structure.

9. 1 x im Jahr Fundamente aufgraben und Stahlfüße auf Korrosion prüfen


Name des Ausführenden

5






Platz für besondere Vermerke, z. B. für Reparaturen

..... Datum

Ersatzteile
Einfachschaukel spezial
Best.-Nr. 3.19802



Bitte beachten Sie, dass das Sicherheitsvolumen des Gerätes nicht verletzt werden darf. Deshalb ist es bei Reparaturen hilfreich, **nur Original-Ersatzteile** einzubauen.

Best.-Nr.	Ersatzteil	Best.-Nr.	Ersatzteil
0.93000	Gummi-Schaukelsitz		
			
0.93010	Gummi-Schaukelsitz mit 4 Ösenschrauben		
			
0.93020	Gummi-Schaukelsitz mit 4 Aufspreizketten		
			
0.93090	U-Bügel mit Drehteil		
			
0.88150	Sinterbuchse für Vierkant		
			
0.20010	V2A-Maschinenschraube M8x55 mit Stoppmutter		
			
0.20020	V2A-Maschinenschraube M8x28 mit Stoppmutter		
	