

Proof of maintenance

This diagram shows an exploded view of a gazebo assembly. The components are numbered as follows: 1. Base plate, 2. Leg, 3. Leg cap, 4. Floor joist, 5. Roof support, 6. Roof panel, and 7. Roof cap.


7. Check for vandalism, replace if metal parts are exposed.

Maintenance carried out by:


..... Date

Special notes, e.g. for repairs

**Spare parts
Meeting House
with Seating Circle
Order No. 7.82300**



Please note that the safety standards of the equipment must not be affected. Therefore, when carrying out repairs it is helpful to **only use original parts.**

Order No. Spare part	Order No. Spare part
<p data-bbox="142 465 679 495">0.93050 Rubber swing seat for adults</p>  <div data-bbox="145 1944 727 2110"> <p>Note This list includes only the spare parts ordered most frequently. Other spare parts on request.</p> </div>	